Temperature and Humidity
WSI-X-AE-TH-1

Measures ambient temperature and humidity.

Tilt Sensor
WSI-X-AE-TS-1

Monitors tilt and low frequency vibrations.

Air Quality Sensor
WSI-X-AE-AQC-1

Measures ambient temperature, humidity and CO2 levels.

I/O Sensor
WSI-X-AE-IO-2AI-2DI-1

2 digital inputs and 2 analog inputs in one sensor

Light Intensity
WSI-X-AE-LS-1

Measures indoor light intensity levels

Door Open-Close Sensor
WSI-X-AE-DS-1

Detects door open/close via switch closure

Modbus Bridge
WSI-X-AE-MB-1

Acts as a RS485 Modbus RTU master. Up to 60 tags can be scanned.

Barometric Pressure Sensor
WSI-X-AE-BPS-1

Measures barometric air pressure.